Check cases Check case 3 pressure gauge + accessories type 2



3 Manometers 0-100; 0-250; 0-400

1 MPR 1/4 with joint

1 MPR 3/8 with joint

1 MPR 1/4 NPT

1 MPR A 10X1

1 MPD 1/4 BSP

1 MPD 1/2 BSP

1 Steel cap

1 MPR PT 1/4 BSP

1 Minimex hose 1000 mm Swivel F - Swivel F; 16X2

1 Minimex hose 2000 mm Swivel F - Swivel F; 16X2

1 MPR 7/16 UNF

1 MPR 9/16 UNF

1 MPR TLM 12L CM

1 MPR 3/8 NPT

Part nº	Size	Scale (bar)
CBOX0002	320x280x119	0-100; 0-250; 0-400